

Church Fire Risk Assessment – May 2025

All Saints Church	Address	
Grayswood	Grayswood Road, Grayswood,	
	Haslemere, Surrey GU27 2DJ	
	Tel. No. 01428 656504	
Church Office Secretary	Fire Officer Safety Co-ordinators	
Sarah Dowd	Diana Ramsden	
	John McLean	
Minister	Assessor	
Revd Fiona Gywnn	Diana Ramsden	

Building Details	
Describe the premises (including construction, brief	Single storey stone and tiled roof
layout – e.g. number of floors linked buildings, etc	construction built 1902 with (no
	significant enclosed roof space)
What are the normal activities undertaken at the	Church Services
premises?	Church office in vestry
	Bell ringing, maintenance and adjustment
	of church clock
What businesses or activities border or adjoin the	None
building which may have a bearing on emergency	
situations or fire safety?	
What are the principal sources of ignition and fuel	Wooden pews, wooden floors and
within the premises?	wooden vaulted ceiling. Candles lit during
	services. Combination boiler in church
	office. Stored items including books,
	vestments and boxes.
Are smoking controls in place and are they observed?	No smoking policy throughout
Have there been fires, vandalism or other problems	No
in the past which may raise fire risk?	
Occupancy Details	
Is the building single or multiple occupancy?	Single
If multiple occupancy who has lead	Not applicable
responsibility	
 On average what is the adult congregation at 	40 approximately
a 10.00am service	
 On average what is the infant/child 	2-3
congregation at a 10.00am service	
 Are there disabled or other mobility impaired 	Yes
people in the building	
Fire Safety Management	
Does the premises have an up to date fire	Yes
certificate?	
Is a copy available for inspection?	Yes, displayed in church office
 If available are there any obvious 	
contraventions or discrepancies?	Not applicable
	1,

Fire Safety Management (cont.)		
Is there a fire alarm and or detection system.	No	
Is it automatic or manual	N/A	
 Does it alert the fire brigade automatically 	N/A	
Does it have a back-up power supply	N/A	
Is it audible throughout the building	N/A	
• Is it suitable for the building, its use and its fire	N/A	
risk	N/A	
What fire extinguishing equipment is in place?	Foam and CO2 portable extinguishers	
	and one dry powder in the basement	
	, ,	
Is emergency lighting present and of what type?	Yes, battery operated	
Fire Detection Systems		
Is the fire alarm and detection system checked by	N/A	
occupant and how often?		
Is emergency lighting checked by occupant and how	Yes, monthly	
often?	res, monthly	
often.		
Is fire extinguishing equipment checked by occupant	Yes, annually	
(i.e. visual check) and how often?	Last inspected March 2025	
Is there evidence of external competent inspection,		
testing and maintenance of:		
fire alarm and detection system	N/A	
fire extinguishing equipment	Yes	
emergency lighting	Yes, 5 yearly by installer	
Fire Action Plan		
Is there a written fire action plan?	Yes	
·		
Is it relevant and appropriate?	Yes	
Does it address and/or identify:		
The action to be taken on hearing an alarm	N/A	
Responsibility for calling the fire brigade	Church Wardens/Sidespeople	
Assembly point	Congregate by church lych gate and	
• Fire marshals/fire officer including the person	assemble on village green.	
who will call the roll/liase with the fire brigade	Church Wardens/Sidespeople	
Fire Control Measures		
Are evacuation drills carried out?	No	
How often	N/A	
Are records maintained	N/A	
Is other fire training carried out?	No	

What type of training	See below:
Is it sufficient for the premises and operations	See Selevi.
carried out	During a Christingle service the congregation are told before the service of the possible risks with lit Christingle candles. • They are made aware that children holding lit Christingles should be stationary and carefully monitored • Both external doors are accessible. • Additional sidespeople are present in case there are any children/candle related incidents. • There are members of the congregation who have medical training and the first aid box in the Church is clearly marked.
Is adequate access control and registration in place to prevent unauthorised access and register those who are on the premises?	No the Church is unlocked during the day Numbers are counted before services
Access Control	
Are escape routes clearly and correctly signed?	No but during a large service/wedding/funeral the congregation are made aware of the external doors. Usually, during a service, both external doors are available for exit, at the front and back of the Church.
Are exit arrangements adequate and in accordance with guidance:	
 Exit doors unobstructed Push bar or other fittings correct Door direction and width in accordance with numbers Exit route travel times and widths adequate for numbers 	Yes N/A Yes Yes
Assessment of Risk	
Overall assessment of risk:	
• L M H	Low
Are there any unsafe situations or defects which have immediate risk to safety?	No
Are there items which require immediate rectification?	No
Record of Inspections	

Portable Appliance Testing (PAT)	Yes
Is this carried out?Date of last PAT	Yes 6 May 2021
Testing of fixed electrical installations	Yes
Testing of fixed gas installations	Yes annual service/inspection of central heating boiler – 05/06/2025

No	Recommendations		Action Taken please sign and date
1	Fire procedures and plans to be reviewed during 2025.		
2	Training of PCC members and sidespeople during 2025		
Sign	ed by Minister:	Signed by Safety Assessor:	
	wynn t name	D Ramsden Print Name	
Date	e: May 2025	Date: May 2025	